CARR-1422

3739 Kump Station Road Taneytown (vicinity)

Summary:

The house at 3739 Kump Station Road is a log structure that was originally part of a farm. In tracing back the property on historic maps, it would appear that the house was owned by S. Wivel in 1862. He was probably the same Saml Wivel listed here in 1877. At this time most of the current Kump Station Road did not exist. The road ran from the turnpike east to the current Bert Koontz Road, then followed this road southward. The maps indicate a private drive from the intersection of these two roads to the east, beyond the Wivel house. Presumably, Wivel oriented his house to face south, and when the current Kump Station Road was created, by 1917, the road was placed to the north of the house. This would have necessitated re-orienting the house to the north, which could explain the alterations to the south wall. In 1917 the farm was 25 acres and was owned by Hezekia [J.?] Honn. The house is unusual for its corner down braces, which pass completely through the horizontal logs of the walls.

MARYLAND INVENTORY OF Maryland Historical Trust State Historic Sites Inventory Form HISTORIC PROPERTIES

Survey No. CARR-1422 Magi No.

DOE __yes __no

1. Nam	16 (indicate	preferred name)			
historic					
and/or common					
2. Loca	ation	arven.		···	
street & number	3739 ' 3839' Kump Stat	ion Road		not for publication	
-11 1	neytown	X— vicinity of	congressional district		
state Mary	_ vland	county	Carroll		
3. Clas	sification				
Category districtX building(s) structure site object	Ownershippublicboth Public Acquisitionin processbeing considerenot_applicab.	X yes: restricted	Present Use agriculture commercial educational entertainment government industrial military	museum park _X private residence religious scientific transportation other:	
4. Owr	ner of Prop	erty (give names	and mailing addresse	s of <u>all</u> owners)	
name Robe	ert & Donna Stem				
street & number 3739 Kump Station Road			telephone no.:756-1023		
	neytown		e and zip code _{Maryl}		
		gal Descript			
courthouse, regi	istry of deeds, etc. Co	urthouse Annex	•	liber ¹ 233	
street & number	55 North Court	Street		folio 760	
city, town Wes	stminster		state	Maryland	
6. Rep	resentatio	n in Existing	Historical Surv	veys .	
title					
date			federal sta	te county loca	
pository for s	urvey records				
city, town			state		

Condition		Check one	Check one			
excellent	deteriorated	unaltered	X original site			
annd	ruins	Y altered	moved date	of move	,	

Survey No. CARR-1422

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

Contributing Resources: 1

unexposed

Description

_ fair

The house at 3739 Kump Station Road is located on the south side of the road and faces north toward it. It is about 2¾ miles northeast of Taneytown in northwest Carroll County, Maryland. It is a two-story, three-bay by two-bay log structure with a parged foundation, aluminum siding, and a corrugated metal gable roof with an east-west ridge. There is an interior brick chimney on each end and a new exterior brick chimney on the west end. On the north elevation the first story has a central door with one light over two flat sunk octagonal panels with bolection mouldings. There is one 6/1 sash on each side. They have been altered and were originally 6/6. There is a one-story, three-bay porch with halfhip roof and asphalt shingles. It has square posts, with jigsawn brackets and a spindlework frieze. The porch deck is now concrete. The second story of the north elevation has three shorter 6/1 sash. There is a box cornice with returns. The east elevation has two 6/1 sash on the first story and two smaller 6/1 sash on the second story. The gable end has two fourlight sash. The west elevation is the same as the east. There was formerly a porch on the south elevation, but it has now been rebuilt as a one-story, shed-roof addition. The house has a two-room plan divided by enclosed winder stairs that run from back to front. There is a hewn summer beam that runs east-west. The joists are also hewn, with a center tenon and peg into the summer beam. The ceiling was previously lathed and plastered. The logs are partly exposed on the interior. They are hewn on the sides. The southeast corner of the building has a vertical corner post. The logs are set into the post, but not pegged to it. This post has corner down braces that go all the way through the logs on the south elevation. it is not possible to determine how the loose ends of the logs are fastened to these corner braces. The south elevation on the first story has exposed logs now. There is a window opening in the east bay. The window frame is nailed to the log ends with cut nails. This south wall has some reused logs that have V-notch cornering, but the corner joints are no longer being used. there was apparently a doorway in the center of the south wall. The header is still in place, but the opening has now been infilled. The second floor joists rest between two logs on the south wall. There is a brick chimney and fireplace on the west end that has been repointed. The fire box, which is small, has been closed off. It has a splayed brick jack arch. The rafters are hewn on top and bottom and have a half-lap and peg at the ridge. The rafter feet have a birdsmouth cut that laps over a false plate attached to the floor in an unknown manner. The rafters have Roman numerals and support lath. The barn burned about 15 years ago.

KS/lh:11-16-94: Carr1422.des

1400 1500 — 1600 — 1700	Areas of Significance—C istoric archeology-prehistoric1499 archeology-historic1599 agriculture1699 architecture1799 art1899 commerce communications		landscape architecture law literature military music t philosophy politics/government	religion science sculpture social/ humanitarian theater transportation other (specify)
Specific	dates	Builder/Architect	· · · · · · · · · · · · · · · · · · ·	<u>.</u>
check:	Applicable Criteria:A and/or Applicable Exception:A	· · · · · · · · · · · · · · · · · · ·	E _ FG	
·	Level of Significance:	_nationalstate	X local	
Prepare	both a summary paragraph	of significance and	a general statement o	of history and

Survey No. CARR-1422

Geographic Organization: Piedmont

support.

Significance

Chronological/Development Period: Agriculture-Industrial Transition A.D. 1815-1870

Historic Period Themes: Architecture Resource Type: Rural vernacular

The house at 3739 Kump Station Road is a log structure that was originally part of a farm. In tracing back the property on historic maps, it would appear that the house was owned by S. Wivel in 1862. He was probably the same Sam¹ Wivel listed here in 1877. At this time most of the current Kump Station Road did not exist. The road ran from the turnpike east to the current Bert Koontz Road, then followed this road southward. The maps indicate a private drive from the intersection of these two roads to the east, beyond the Wivel house. Presumably, Wivel oriented his house to face south, and when the current Kump Station Road was created, by 1917, the road was placed to the north of the house. This would have necessitated re-orienting the house to the north, which could explain the alterations to the south wall. In 1917 the farm was 25 acres and was owned by Hezekia [J.?] Honn. The house is unusual for its corner down braces, which pass completely through the horizontal logs of the walls.

KS/lh:11-28-94:Carr1422.sig

9. Major Bibliographical References

Survey No. CARR-1422

1862, 1877, 1917 maps

Zone Easting Northing Zone Easting Northing C	
F H H H H H H H H H H H H H H H H H H H	
List all states and counties for properties overlapping state or county boundaries state code county code state code county code	
state code county code state code county code	
state code county code	
11. Form Prepared By	×
name/title Kenneth M. Short, Historic Planner	
organization Carroll County Planning Department date December 8, 1994	
street & number 225 North Center Street telephone (410) 857-2145	
city or town Westminster state Maryland	

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House

21 State Circle


Annapolis, Maryland 21401 (301) 269-2438

MARYLAND HISTORICAL TRUST

DHCP/DHCD 100 COMMUNITY PLACE


CROWNSVILLE, MD 21032-2023


-514-7600







DISTRICT Nº1











3739 Kury Station Rd. Carroll County, Maryland

Photo: Kenneth M. Short

Date: Oct. 1994 Neg. Loc. Maryland Historical Trust north elevation